



**LEGEND**

- Sidewalk Condition - Fair
- Sidewalk Condition - Poor
- Bus Route
- Bus Stop
- Intersection Signal Condition  
Pedestrian Signal Heads,  
Clearly Striped Crosswalks,  
and Curb Ramps
- Possible Pedestrian Signal  
Heads, Poorly Striped  
Crosswalks, and Some Curb Ramps
- No Pedestrian Signal Heads,  
Few Crosswalks, and Almost  
No Curb Ramps

Morris County Department of Engineering

East Hanover Avenue  
Corridor Study

Multimodal Survey

Scale: 1" = 800' EXHIBIT 4